

Menu


HISTORY FILE MAP for year 2007

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK



283.12:17-12:35

18m realtime 1024 bps lost due to planned gap between DSS-32 and DSS-63 followed by:
1hr 31m realtime 1024 bps lost due to power failure of LNA at DSS-63. Telemetry was restored following power cycling of LNA rack. DR M104460 refers.

283.12:36-14:07

282.14:54-15:38

5m realtime 512 bps and 38m realtime 1024 bps lost due to DSS-54 failure to transfer predicts to antenna pointing control unit. DR M104447 refers.